

عنوان قرارداد:

تعمیر، بازسازی، نگهداری حین تعمیر، تهیه و تامین قطعات و

تجهیزات دکل حفاری دریایی سینا ۱

کارفرما: شرکت پترو گوهر فراساحل کیش

پیمانکار: شرکت مهندسی اندیشه و عمران محیط



شرکت مهندسی
اندیشه و عمران محیط



شرکت پترو گوهر
فراساحل کیش

مدارک نهایی تعمیرات:

ضخامت سنجی

Divider No.	Subject	INDEX	Page
Volume 1- General Document			
1	MPI Equipment Summery		1
2	UT Surface Summery		25
3	UT Pipe Summery		41
4	Phase Array Summery		43
5	Certificate Documents		45
6	Magnetic Particle Test Procedure		55
7	Ultrasonic Testing Procedure		63
8	Phased Array Procedure		72
Volume 2- UT surface			
1	Tank 7cl		1
2	Tank 7p		29
3	Tank 2p		133
Volume 3- UT surface			
1	Tank 6s		1
2	Tank 3p		79
3	Tank 3s		91
4	Tank 3s, 3p		112
5	Tank 4s		120
6	Tank 4p		150
Volume 4- UT surface			
1	Tank 7s		1
2	Tank 6p		83
Volume 5- UT surface			
1	Tank 1cl		1
2	Tank 2s		94
Volume 6- UT surface			
1	Main Deck		1
2	Air Service		69
3	Aux Room		75
4	Engine Room		86
5	Sack Room		90
6	Crane Tank		97
7	Shale Shaker		109
8	Mud Gas		132
9	Mud Pump Room		135
10	Cement Room		139
11	Barit Room		148
Volume 7- Phase Array			
1	Report No.1		1
2	Report No.2		34
3	Report No.3		67
4	Report No.4		100

Divider No.	Subject	INDEX	Page
5	Report No.5		133
6	Report No.6		166
7	Report No.7		199
8	Report No.8		232
9	Report No.9		266
10	Report No.10		300
11	Report No.11		320
Volume 8- Phase Array			
1	Report No.12		1
2	Report No.13		35
3	Report No.14		68
4	Report No.15		83
5	Report No.16		128
6	Report No.17		165
7	Report No.18		200
8	Report No.19		233
9	Report No.20		266
10	Report No.21		299
11	Report No.22		317
Volume 9- UT Pipe Thickness			
1	Salt Water		1
2	Bilge & Ballast Drainage System		50
3	Sea Water		68
4	High Pressure MUD Line		72
5	Low Pressure MUD Line		116
6	Drill Water		167
7	Dray Bulk MUD		171
8	Cement & Dray Bulk MUD		190
9	Cement		200
Volume 10- MPI Equipment			
1	Report No.1		1
2	Report No.2		2
3	Report No.3		6
4	Report No.4		8
5	Report No.5		12
6	Report No.6		20
7	Report No.7		26
8	Report No.8		29
9	Report No.9		30
10	Report No.10		32
11	Report No.11		34
12	Report No.12		38
13	Report No.13		42
14	Report No.14		44

Divider No.	Subject	INDEX	Page
15	Report No.15		46
16	Report No.16		48
17	Report No.17		53
18	Report No.18		55
19	Report No.19		60
20	Report No.20		62
21	Report No.21		67
22	Report No.22		69
23	Report No.23		70
24	Report No.24		71
25	Report No.25		73
26	Report No.26		78
27	Report No.27		81
28	Report No.28		82
29	Report No.29		91
30	Report No.30		93
31	Report No.31		98
Volume 11- MPI Equipment			
1	Report No.1		1
2	Report No.2		13
3	Report No.3		24
4	Report No.4		25
5	Report No.5		28
6	Report No.6		32
7	Report No.7		47
8	Report No.8		62
9	Report No.9		77
10	Report No.10		83
11	Report No.11		87
12	Report No.12		89
13	Report No.13		98
14	Report No.14		102
15	Report No.15		109
16	Report No.16		111
17	Report No.17		113
18	Report No.18		123
19	Report No.19		126
20	Report No.20		127
21	Report No.21		129
22	Report No.22		131
23	Report No.23		134
24	Report No.24		136
25	Report No.25		142